














## B27 Fräswendeplatten und Schnittdaten

Milling inserts and parameters, Plaquettes de fraisage et paramètres, Inserti e parametri di taglio

			HC45 (code 41)	XC35 (code 46)	HT20 (code 32)	K15M (code 8)		
	<b>JMB27-T09GRR08-</b> IK 9,52x4,62 R0,8	Order- No.	<b>B27B-PZ41</b>	<b>B27B-NH46</b>	<b>B27B-AS32</b>			
	 	$f_z$ [mm]	0,15 (0,10-0,30)	0,15 (0,10-0,30)	0,20 (0,15-0,30)			
	<b>JMB27-T09GR08-</b> IK 9,52x4,62 R0,8	Order- No.	<b>B27B-OU41</b>	<b>B27B-UA46</b>	<b>B27B-PY32</b>			
	 	$f_z$ [mm]	0,15 (0,10-0,30)	0,15 (0,10-0,30)	0,20 (0,15-0,30)			
	<b>JMB27-T09GRR02-</b> IIK 9,52x4,62 R0,2	Order- No.				<b>B27B-WP08</b>		
	 	$f_z$ [mm]				0,20 (0,15-0,30)		
	<b>JMB27-T09GR02-</b> IK 9,52x4,62 R0,2	Order- No.				<b>B27B-XT08</b>		
	 	$f_z$ [mm]				0,20 (0,15-0,30)		
			20	20	20	20		

$V_c$ [m/min]	Stahl Steel Acier Acciaio	Rostfrei Stainless Acier inoxydable Inossidabile	Guss Cast iron Fonte Ghisa	NE-Metalle Non-ferrous metals Non ferreux Metalli non ferrosi	Hochwarmfest Highly heat-resistant Superalliages Resistente al calore	Gehärtet Tempered Aciers traités Temprato
<b>HC45</b>	250 (200 - 350)	240 (140 - 300)	240 (130 - 280)			
<b>XC35</b>	120 (60 - 160)	100 (60 - 180)			80 (40 - 200)	
<b>HT20</b>			260 (180 - 350)			80 (40 - 120)
<b>K15M</b>				400 (300 - 600)		

### Ersatzteile Spare parts, Pièces de rechange, Parti di ricambio

	<b>SS 4,0-10</b> (M = 3,2-3,3 Nm)		<b>T 15+</b>		<b>Fett</b> Grease, Graisse, Grasso
---	--------------------------------------	---	--------------	---	--